

# Product Safety Recall



**NISSAN D40 NAVARA / PATHFINDER FRONT EXTENDED BALLJOINTS**  
PSRNAV-001 / AND BALL JOINTS ON PSRNAV-009  
Sold 17<sup>th</sup> April 2015 – 8<sup>th</sup> May 2016

**Defect** In some circumstances the ball joints will fail and causes potential separation of ball joint components.

**Hazard** If the defect occurs whilst in use the ball joint can separate making the suspension system fail which may cause serious injury or death to the user.

**What to do** Consumers should immediately stop using the ball joints and contact Performance Suspension to receive a set of replacement ball joints or a full refund of the purchase price.

**Contact Details** You can contact Performance Suspension by phoning (07) 5529 2366 Mon – Fri 8:00am – 5:00pm, via email at [info@performancesuspension.com.au](mailto:info@performancesuspension.com.au) or go to [www.performancesuspension.com.au](http://www.performancesuspension.com.au)

**See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information**